



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 21, 2008

Reviewer SW

Mine Name: TME Asphalt Ridge	Permit Number: M0470089
Operator Name: TME Asphalt Ridge LLC	Inspection Date: 05-21-08
Inspector(s): L Heppler	Time: 4:00 pm
Other Participants: Tony Hite, Jody Atwood	Mine Status: Act

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 04-11-2009 **Bond Amount:** \$18,600 This mine is converting to a LMO (M0470089)

Purpose of Inspection: This was a routine annual inspection.

Inspection Summary: Environmental fence as been installed next to drainage. No trash or safety hazards noted. Main access road has been paved. No topsoil has been stockpiled at this time.

Conclusions and Recommendations: Continue to monitor this site when in the area.

Photos were taken to document site conditions.

Inspector's Signature

LAH:pb

cc: TME Asphalt Ridge LLC

FEE

P:\GROUPS\MINERALS\WP\M047-Uintah\M0470089-TMEAsphaltRidge\draft\Insp_TMEAsphaltRidge_05-21-08.doc

Photos Taken 05-21-08

